

## RhinoCAM General Info

Opening RhinoCAM- select **Mill** from menu.

Programming Workflow- use **Machining Browser (MOps)** dialogue box

### 1) **Program Tab- Machine Setup**, and defining **Stock**

#### A) **Machine**

- i) Select "Manual Definition."
- ii) Machine Type: Number of Axes- select 3 Axis

#### B) **Post**- select "Technisel" from current post processor menu.

#### C) **Stock**- "Box Stock" is most common selection.

- i) Draw a rectangle in X & Y planes to form perimeter of stock.

#### D) **Align**

- i) Align Stock and Part- dependent upon location of object within workpiece for Z alignment, and XY alignment.
- ii) Set World C.S.
  - a) Set WCS Origin- select "set to stock box"
  - b) Zero Face- select "highest Z"
  - c) Zero Position- select "South West"

### 2) **Program Tab- creating Machine Operations** (2 & 3 Axis)

#### A) **Tool**- download cutting tool library from Architecture's homepage: Student Groups & Resources > Woodshop/Digital Fabrication Shop (view resources) > RhinoCAM Tool Library

- i) Select Compression Cut cutter (1/4" or 1/2") when cutting plywood in order to prevent tearing of top and bottom surface.

#### B) **Feeds & Speeds**

- ii) Default feeds and speeds are preset for the cutters in the downloadable library.
- iii) If using cutters other than those in the library, use the following default settings:
  - a) Spindle Parameters- 18,000 RPM (1/4" tooling and smaller), 9,000 RPM (1/2" tooling)
  - b) Feed Rates (in/min)- Plunge= 30; Approach= 200; Engage= 200; Cut= 250; Retract= 30; Departure= 200
- iv) Actual feeds and speeds will be set at time of milling using milling calculator (only on computer in rm 109). Defaults allow for estimate of milling time.

#### C) **Cut Parameters**

- i) Cut Direction- when cutting plywood, select "Climb (down cut)" to prevent tear out of surface.

#### D) **Cut Levels**

- i) Rough Depth/Cut- the depth of each individual cutting pass, relative to the total cut depth.
  - a) Must be set at no more than half the diameter of the cutter (ie. 1/2" cutter- rough depth/cut= 1/4"). Foam can be cut to a depth of the full flute length (view individual tools for specifications)

#### E) **Advanced Cut Parameters**

- i) Bridges/Tabs- must be made to prevent workpiece from being thrown when cutting is complete (check Create Bridges box)
  - a) Positioning of automatic bridge/tabs is determined by selecting either the number of bridges, or the distance between bridges.

- ii) Manual bridge points- allows for specific positioning of individual bridge points (creation of manual bridge points must be completed in specific order)
  - a) Create machining region set (in **Machining Objects Browser**)
  - b) Create machining operation (2 Axis operations)
    - i) Control Geometry > Select Pre-Defined > select machine region set
    - ii) Advanced Cut Parameters > Bridge/Tabs > check box and size tabs, and select either number of bridges or distance between bridges.
    - iii) Generate file > then Simulate.
  - c) Select Manual Bridge Points on Selection (in **Machining Objects Browser**) > select points
  - d) Regenerate file (right click on file for menu options) > then Simulate
- F) Right-clicking on MObs file
  - i) Information- gives estimate of cutting time

Programming Workflow- use **Machining Objects** (MOps) browser dialogue box

- 1) **Tools** tab
  - A) View individual cutters in library for specifications, and feeds and speeds
- 2) **Regions** tab
  - A) Regions are individual or groups of curves combined to determine cutting paths
    - i) Best practice is to pre-select curves using Curve > Curve From Object > Duplicate (Edge/Border/Face Border/Mesh Edge)